

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|-----------------------------|--|-------------------------|-------|------|
| PERMIT NO. <i>A-1821</i> | LOCATION <i>1055 Santa Ursula Way</i> | | | |
| DATE <i>7/10/34</i> | PURPOSE <i>To add kitchen to</i> | PHONES <i>of the</i> | | |
| ZONE <i>Mult. Fam</i> | OWNER <i>Wm L. Lewis</i> | | | |
| | ARCH'T <i>Quincy</i> | | | |
| | CONT'R <i>Quincy</i> | | | |
| VAL. <i>100.00</i> | STORIES | ROOMS | APTS. | SIZE |
| Light Shafts | | Elevator Shafts | | |
| Vent Shafts | | Boiler Rooms | | |
| Owner's Inspector | | Sprinkler System | | |
| Lath | | Gas Vents | | |
| Fire Escapes | | Chimneys | | |
| Stand Pipes | | Skylights | | |

| DATE | CONDITION OF WORK-REMARKS |
|---------|--|
| 7/10/34 | Made Pullman in Sub A outside Kitchen & Repair to rear of Body. H.W. Campbell |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p> |