

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-38997		LOCATION 561 Santa Ynez Way			
DATE 9-28-53		PURPOSE Add room onto rear of dwlg			
ZONE		OWNER E. F. Cadden			
		ARCH'T.			
		CONTR. "			
VAL. \$1500		STORIES	ROOMS	APTS.	SIZE 200 sq ft
LIGHT SHAFTS				ELEVATOR SHAFTS	
VENT SHAFTS				BOILER ROOMS	
OWNER'S INSPECTOR				SPRINKLER SYSTEM	
LATH				GAS VENTS	
FIRE ESCAPES				CHIMNEYS	
STAND PIPES				SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
10-5-53	Form Don Berney
10-15-53	Flange joint " "
11-10-53	Frame " "
1-13-54	Final Don Berney
	<p data-bbox="349 857 470 895">COMPLETE AND O. K.</p> <p data-bbox="1165 871 1291 888">INSPECTOR</p>