


BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3697</i>	LOCATION <i>3441 - 13<sup>th</sup> Street</i>
DATE <i>8/26/39</i>	PURPOSE <i>erect new dwlg - gar</i>
ZONE <i>v-Hom</i>	OWNER <i>Robert O. Faristyne</i>
	ARCH'T. <i>L. L. Watson</i>
	CONTR. <i>L. L. Watson</i>

VAL. <i>5748<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS	BOILER ROOMS	<i>1600<sup>00</sup></i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 350</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
8/29/39	1 <sup>st</sup> Insp Formis ok Pictor
9/21/39	2 <sup>nd</sup> Insp. Frame in place <sup>OK</sup> M. Campbell
7/26/39	3 <sup>rd</sup> Insp. INT & EXT work <sup>OK</sup> M. Campbell
11/9/39	4 <sup>th</sup> Insp. Dura & Garage Completed
.. ..	Issued Final Insp. & Cert. of Occip.
.. ..	Street cleaned up ok
11/9/39	<div style="display: flex; justify-content: space-between; align-items: center;"> <span data-bbox="291 872 417 913">COMPLETE AND O. K.</span> <div data-bbox="445 841 1061 934" style="text-align: center;">  </div> <span data-bbox="1117 882 1243 909">INSPECTOR</span> </div>