

R206 F 362

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

PERMIT NO. F-5858	LOCATION 1055 - Santa Ynez Way A-1
DATE Nov 10-66	PURPOSE Repair termite damage to dwelling
ZONE R-1	OWNER William Lewis Same
	ARCH'T GI 8-1882
	CONT'R Valley Termite 1617 - 18th St.

VAL. \$900.	STORIES	ROOMS	APTS.	SIZE
-------------	---------	-------	-------	------

INSP.	DATE	BLDG. TYPE	V	OCCUPANCY GROUP	I-1	PHONE (O) (C)
-------	------	------------	---	-----------------	-----	---------------

FORM	11/17/66	Cont
------	----------	------

JOIST		
-------	--	--

FRAME	11/19/66	Cont
-------	----------	------

SHEET ROCK		
------------	--	--

FINAL	11/25/66	E. Larson	ent
-------	----------	-----------	-----

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR