

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>Rocky</i>	LOCATION <i>2324 4 St</i>			
DATE <i>9/26/31</i>	PURPOSE <i>Gen Rep Beam Loading Platform</i>			
ZONE <i>Em Com</i>	OWNER <i>Walter Holmes</i>			
	ARCH'T			
	CONT-R <i>W.P. Leland</i>			
VAL. <i>Under 100</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE

CONDITION OF WORK-REMARKS

**COMPLETE
AND O.K.**

INSPECTOR

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>No Charge</i>	LOCATION <i>APEX DAIRY 2324 Y St.</i>			
DATE <i>June 24, 1930</i>	PURPOSE <i>Install 1-570 gal Fuel Oil Tank and 1-285 gal Gas Tank located 5 ft or more from any bldg on lot and 1-1 gal. Hand Pump.</i>	PHONES		
ZONE <i>General Commercial</i>	OWNER <i>APEX DAIRY</i>	ARCHT		
VAL.	CONT'R <i>UNION OIL Co, Mail Bldg</i>			
<i>150⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS.
	<p data-bbox="317 878 486 930">COMPLETED AND O.K.</p> <p data-bbox="1185 905 1345 936">INSPECTOR</p>