

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2862</i>	LOCATION <i>401 - Pala Way.</i>
DATE <i>4/14/39</i>	PURPOSE <i>Erect new dwlg. apt.</i>
ZONE <i>1</i>	OWNER <i>Jack Blake</i>
	ARCH'T. <i>C. C. Ruby</i>
	CONTR. <i>C. C. Ruby</i>

VAL. <i>4500⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK-REMARKS	
4/18.39	15	Lump Form on Putter
3/8.39	2	" Frame " Putter

COMPLETE
AND O. K.

INSPECTOR