

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-944</i>	LOCATION <i>5838-5th Ave.</i>
DATE <i>Sept. 14-33</i>	PURPOSE <i>To const concrete base ment under dwell.</i>
ZONE <i>2-Fam.</i>	OWNER <i>Mr. Local.</i>
	ARCH'T <i>Angelo &amp; Frank-</i>
	CONT-R

VAL. <i>4500</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

RECORDED AT THE OFFICE OF THE CLERK OF THE BOARD OF HEALTH  
 SEP 22 1933

DATE	CONDITION OF WORK-REMARKS
9/12/33	<p>Notified &amp; get the Portland Cement          An insta 6' x 14' Rebar and a sec          of Dwg with notes. Concrete thick &amp; same</p>
9/14/33	<p>Inspect - Forms ok All Cement</p>
	<p>COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span></p>