

K967 278

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$5.00

## TYPE BUILDINGS

PERMIT NO. <b>E-717</b>	LOCATION <b>3198 - Land Park Drive</b>		<b>A-2</b>	
DATE <b>Mar. 1-62</b>	PURPOSE	<b>Remodel room to bathroom in dwelling.</b>		
ZONE <b>R-1</b>	OWNER	<b>William Dwyer</b>	<b>Same</b>	
	ARCH'T	<b>GI 8-8241</b>		
	CONT'R	<b>State-Wide Const. 1209-21st Street</b>		
VAL. <b>\$200.</b>	STORIES	ROOMS	APTS.	SIZE <b>120 sq. ft.</b>
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	
FORM				
JOIST				
FRAME	<b>3-7-62</b>	<i>Count</i>		
SHEET ROCK	<b>3-13-62</b>	<i>Boards</i>		
FINAL	<b>4-6-62</b>	<i>Dana Fuller</i>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR