

R 281 F574

| | | | | | |
|----------------------|--|--|-----------------|-------------------------------|---------------------|
| Lot 685 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$62.00 |
| Southgate Meadows #8 | | TYPE BUILDINGS | | | R259 F572-576 Plans |
| PERMIT NO. G-6932 | LOCATION 7724 - Millroy Way A-5 (49) | | | | |
| DATE May 22-70 | PURPOSE Const. dwelling & att.gar. MP 1001 A | | | | |
| ZONE R-1 | OWNER Aguilas, Inc. 2777 Alvarado S. Leandro | | | | |
| | ARCH'T | | | | |
| | CONT'R Besco Builders Inc. same 483-4300 | | | | |
| VAL. \$15,600. | STORIES | ROOMS | APTS. | 340-gar. SIZE 1,032-sq.ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | 6-9-70 | Hammers | | | |
| JOIST | | | | | |
| FRAME | 7-1-70 | Miller | | | |
| SHEET ROCK | 7-10-70 | Hammers | | | |
| FINAL | 8-3-70 | E. Hansen | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--------------------------------------|
| 6-1-70 | Pt not steady <i>Rick</i> |
| 6-11-70 | slab - <i>Hammers</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR