

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-10,845	LOCATION 2331-Riverside Blvd.
DATE 11/2/42	PURPOSE Repairs to understructure
ZONE	OWNER M. Blackwood
	ARCH'T.
	CONTR. Opaymore

VAL 40500	STORIES 1	ROOMS 1	APTS.	SIZE
------------------	------------------	----------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS—
	COMPLETE AND O. K. INSPECTOR