

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		LEGAL DESCRIPTION		TITLE AND NAME		GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.		MECH. CONTR.		ARCH. ENGR.		OWNER		CONST. LOAN LENDER																									
		5770 Bellview Avenue		5770 Bellview Avenue		5770 Bellview Avenue																																							
DATE		BUILDING BY		DATE		ELECTRICAL BY		DATE		PLUMBING BY		DATE		MECHANICAL BY		DATE		CERTIFICATE OF OCCUPANCY		ISSUED BY		DATE																							
INSPECTION AREA		VAR. NO.		CONST TYPE		OCCUP. GR.		TOTAL AREA		CENSUS TRCT. NO.		C.I. CASE		HOW USED		SIDE YARDS		REAR YARDS		SET BACK REQ.		USE ZONE		PARK'G REQ.		SPACES		TREES RMVD.		EXISTING BLDG'S SAME LOT		TOTAL AREA		AREA 1st FLOOR		ROOF CONSTR.		NO. OF STORIES		TOTAL HEIGHT		BLDG. LENGTH		BLDG. WIDTH	
4																																													

NATURE OF WORK:-

PERMIT NO. S.P.	
ISSUED BY	
PLANS AND APPLICATION	REEL NO. FRAME NO. TO
VALUATION	REEL NO. FRAME NO. TO
R.O.F. FEE	JOB FILE
S.M.I. FEE	
PLAN CK. FEE	
SEWER INCL. FEE	
PERMIT FEE	
TOTAL FEES	

REMARKS AND/OR VARIANCES

8-5-75 floor - 15 80% dirt floor & much debris & old lumber
 13 bagging around. Done for better at expiration per D. Fuller
 8-7-75 floor of lot expiration per - 103 - ml. 8-15-75
 30-day permit. 8-19-75 spots with 1/2" dia. in. No water to give the ground
 30-day permit. - Dwelling 577. to 9-19-75 status check back in.