

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4247</i>	LOCATION <i>761 - Robertson Way</i>
DATE <i>12/19/40</i>	PURPOSE <i>Erect new dwlg &amp; gar</i>
ZONE	OWNER <i>W. E. Cold</i>
	ARCH'T.
	CONTR. <i>C. L. Glisan</i>

VAL. <i>4000</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i> <i>834'</i> <i>@ 300</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
12/20/40	1 <sup>ST</sup> / NSP. Frames in place. <sup>OK</sup> M. W. Campbell
1/10/41	2 <sup>ND</sup> / NSP. Frames . . . . . <sup>OK</sup> M. W. Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="301 832 425 871">COMPLETE AND O. K.</span> <span data-bbox="1126 850 1258 871">INSPECTOR</span> </div>