

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

M-21-18

PERMIT NO. <i>B-2 F 128</i>	LOCATION <i>3920. W. Ld. Pk. Dr.</i>
DATE <i>2-10-50.</i>	PURPOSE <i>Erect Cafeteria</i>
ZONE	OWNER <i>Holy Spirit School</i>
	ARCH'T.
	CONTR. <i>L. Bennett</i>

VALU [#] <i>16,140</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK-REMARKS
5/22/50	No Form Insp. Called For A. E. Puchins
5/22/50	Wall Steel & Bond Beam Insp. "
6/28/50	Frame (Beams on roof (2) are not strong enough add 2x8 at each beam) M A Shumway
COMPLETE AND O. K.	INSPECTOR