



BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A1521</i>	LOCATION <i>2723 - Jct.</i>
DATE <i>3/31/34</i>	PURPOSE <i>Remod front of demerol.</i>
ZONE <i>Mt. Jan</i>	OWNER <i>James Slovitch.</i>
	ARCH'T <i>Mr. B. Ladner</i>
VAL. <i>750 =</i>	STORIES
	ROOMS
	APTS.
	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
4/1/34	1 ST WSP. Frame for Addition on Front of Store for new Bricks & Re-dry Concrete Block Steps and enlarging room on both upper & lower floor ^{OK} A.W. Campbell
4/20/34	2 ND WSP. Frame for above ^{OK} A.W. Campbell
4/27/34	3 RD WSP. In-lane for Addition ^{OK} A.W. Campbell
6/22/34	4 TH WSP Alterations, Addition & Re-bricks Completed ^{OK} 
6/22/34	COMPLETE AND O. K.  INSPECTOR