

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-71</i>	LOCATION <i>3001 Oh Street</i>
DATE <i>10-19-32</i>	PURPOSE <i>Re-roof Bldg used as ^{PHONES} Dwelling & Bus.</i>
ZONE <i>Multiple Dwelling</i>	OWNER <i>Sadie King</i>
	ARCH'T
	CONT-R <i>Owner</i>
VAL. <i>\$150.00</i>	STORIES
	ROOMS
	APTS.
	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
10/26/37	Partial Insp of Re Roofing over shingled Roof with Composition Shingles A W Campbell
11/15/37	Final Insp. Re Roofing of Bldg Completed O.K. A W Campbell
11/15/37	COMPLETE AND O. K. <i>Alfred W Campbell</i> INSPECTOR