

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO.

LOCATION

908 - 8th Street

DATE

PURPOSE

Repairs to Building due to fire

OWNER

Mrs John Loddick

ZONE

ARCH'T.

CONTR.

John Loddick

VAL.

STORIES

ROOMS

APTS.

SIZE

4900⁰⁰LIGHT
SHAFTSELEVATOR
SHAFTSVENT
SHAFTSBOILER
ROOMSOWNER'S
INSPECTORSPRINKLER
SYSTEM

LATH

GAS
VENTSFIRE
ESCAPES

CHIMNEYS

STAND
PIPES

SKYLIGHTS

DATE.	CONDITION OF WORK—REMARKS
7/16/43	1 ST /HSP. Forms for New Cement Floor in Basement. O.K. A.W. Campbell
7/16/43	2 ND /HSP. Frame for Bldg. ^{of} Fireless A.W. Campbell 3 RD /HSP. Lab. Basement - Lath by J.R. Shields
8/11/43	3 RD /HSP. Main Story Walls & Ceiling Lath with ^{O.K.} 3/8" Rock Lath on Walls & Metal Lath on Ceiling. A.W. Campbell
10/15/43	4 TH /HSP. Remodeling & Repairs Completed O.K.
10/15/43	COMPLETE AND O. K. Alden W. Campbell INSPECTOR