

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2465</i>	LOCATION <i>1136 - Teneight Way</i>			
DATE <i>2/15/39</i>	PURPOSE <i>New dwlg. + gar</i>			
ZONE <i>2 fam.</i>	OWNER <i>Fredrick J. Chapel</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>5300⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	<i>1767⁰⁰</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 350</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
1/27-39	1 st Insp Form of District
3/14-39	2 " Form of District
6/20-39	3 " Lath & Plaster
5/25-39	4 " Form of District

COMPLETE
AND O. K.

INSPECTOR