

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-530</i>	LOCATION <i>1511 - 3rd St</i>			
DATE <i>4/16/40</i>	PURPOSE <i>Erect new stone Bldg</i>			
ZONE	OWNER <i>Mendoza &amp; Sons</i>			
	ARCH'T.			
	CONTR. <i>Edward S. Sigler &amp; Co.</i>			
VAL. <i>1000</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
4/18/40	1 <sup>ST</sup> INSP. Form in place <sup>OK</sup> R.W. Campbell
6/12/40	2 <sup>ND</sup> INSP. (Part of) <sup>Back to top of roof</sup> Machine R.W. Campbell
6/18/40	2 <sup>ND</sup> INSP. Bulb of frame <sup>OK</sup> R.W. Campbell
6/25/40	3 <sup>RD</sup> INSP. INT. PART <sup>OK</sup> R.W. Campbell
7/8/40	4 <sup>TH</sup> INSP. Store Bldg Condition <sup>OK</sup>
7/8/40	COMPLETE AND O. K. <i>Allen S. Campbell</i> INSPECTOR