

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
2809 Marmor Court		A-1		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
Lot 383 Glenbrook #4					
TITLE AND NAME					
1/c Besco					
GEN. CONTR.					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
Valbrook, Inc.					
CONST. LOAN LENDER					
BLDG. WIDTH					
BLDG. LENGTH					
TOTAL HEIGHT					
NO. OF STORIES					
ROOF CONSTR.					
AREA 1st FLOOR					
TOTAL AREA					
C.S.D.					
C.I. CASE					
ISSUED BY					
DATE					
CERTIFICATE OF OCCUPANCY					
2777 Alvarado Street					
SIDE YARDS					
REAR YARDS					
SET BACK REQ.					
USE ZONE					
PARK'G. REQ.					
SPACES					
TREES RMVD.					
EXISTING BLDG'S SAME LOT					
HOW USED					
CENSUS TRCT. NO.					
1394 sq ft					
TOTAL AREA					
500 gar.					

NATURE OF WORK:- Const. Dwelling & Att Garage

PERMIT NO. S.P.	F-6548
ISSUED BY	
ISSUANCE DATE	2-28-67
VALUATION	\$ 13,800
R.U.F. FEE	\$
S.M.I. FEE	\$
PLAN CK. FEE	\$
SEWER INCL. FEE	\$
PERMIT FEE	\$ 49.
TOTAL FEES	\$

PLANS AND APPLICATION	REEL NO. 271	FRAME NO. 128	TO 579	TO 579
INSPECTION RECORD	REEL NO. 578	FRAME NO. 578	TO 579	TO 579
JOB FILE	REEL NO.	FRAME NO.	TO	TO
REMARKS AND/OR VARIANCES				
MICROFILM RECORD				