

R 231 F 346

| | | | | | |
|----------------------|-----------------|--|-----------------|----------------------------------|------------------------------|
| Lot 491 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$55.00 |
| Southgate Meadows #6 | | TYPE BUILDINGS | | R229 F 60-50 71-80 | |
| PERMIT NO. | LOCATION | | | | |
| F-9317 | 27 Tillman Cir. | | A-5 | | |
| DATE | PURPOSE | Const. dwlg & Gar. Master Plan 101-LC | | | |
| 1-10-68 | OWNER | Valbrook, Inc. 2777 Alvarado St. San | | | |
| ZONE | ARCH'T | Leandro, CA | | | |
| | CONT'R | Besco | same | 383-9315 | |
| VAL. | \$15,100. | STORIES | ROOMS | APTS. | 456 gar. SIZE 1525 sq.ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | 1-23-68 | Check | | | |
| JOIST | 1-29-68 | Check | | | |
| FRAME | 3-5-68 | Check | | | |
| SHEET ROCK | 3-9-68 | Check | | | |
| FINAL | 4-26-68 | Check | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 1-19-68 | PK Beam - Not ready Count |
| 1-20-68 | OK slab Count |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p> |