

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10391</i>	LOCATION <i>107 - Tivoli Way</i>			
DATE <i>5/22/42</i>	PURPOSE <i>Eject new dwly & gar</i>			
ZONE	OWNER <i>Mary E. Phillips</i>			
	ARCH'T.			
	CONT'R. <i>W. B. Phillips</i>			
VAL <i>3000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>4</i>	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>area 7850' @ 355</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
8/19/42	Is Sub Forms OK. Kauter
9/27/42	The skeleton frame is erected with
9/10/42	2 NO/NSP. Frame. OK M. Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>