

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 6671</i>	LOCATION <i>3421 Truckee Way</i>
DATE <i>10/7/40</i>	PURPOSE <i>New dwg & garage</i>
ZONE <i>—</i>	OWNER <i>Arnold & Opdyke</i>
	ARCH'T. <i>Paul Opdyke</i>
	CONTR. <i>Paul Opdyke</i>

VAL. <i>3500⁰⁰</i>	STORIES <i>7</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>925⁰⁰</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 30'</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS	
10/9	1 st	Lump Formed Oil Patch
11-18	2 nd	" Frame & Patch
11-28	3	" " Patch
		<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>