

P205 F131

Lot 333 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$49.00

TYPE BUILDINGS

Q180 F276-287 plans

Glenbrook #4

PERMIT NO. F-5606	LOCATION 8562 - Merribrook Drive A-1			
DATE Oct 13-66	PURPOSE Const. dwlg. & gar. Plan 402			
ZONE R-1	OWNER Estructuras, Inc. 2777-Alvarado St.			
	ARCH'T Besco		San Leandro, Calif.	
	CONTR Same		363-7315	
VAL. \$13,800.	STORIES 1	ROOMS 5	APTS.	500 gar. SIZE 1,394 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM	<i>10/19/66</i>	<i>Larson</i>		
JOIST	<i>11/1/66</i>	<i>Larson</i>		
FRAME	<i>11/22/66</i>	<i>Hammers</i>		
SHEET ROCK	<i>12/2/66</i>	<i>Larson</i>		
FINAL	<i>2-10-68</i>	<i>[Signature]</i>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
11/24/66	OK	Slab
11/25/66	PT	Frame - Not ready
		Linen
		Callings
COMPLETE AND OK	INSPECTOR	