

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>9584</i>	LOCATION <i>917-12th St</i>
DATE <i>1/27/31</i>	PURPOSE <i>Install Office Floor</i>
ZONE <i>Gen Com</i>	OWNER <i>V B Co.</i>
	ARCH'T
	CONT'R <i>Campbell Const Co</i>

PHONES

VAL. <i>9072 -</i>	STORIES	ROOMS	APTS.	SIZE
-----------------------	---------	-------	-------	------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boller Rooms	
Owner's Inspector Rfcd, Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS
1/27/31	Made Preliminary Inspection on 2 nd Story of Bldg. to be finished for Office Windows to be installed in Brick Walls and new Sashlight installed in Rock. etc. <i>Al W. Campbell</i>
2/2/31	2 nd /N.S.P. Frame for Office 2 nd Story <i>Al W. Campbell</i>
2/3/31	3 rd /N.S.P. INT. LATH (Rock Wall) Plaster and ^{Walls & Ceilings} 2 nd Story <i>Al W. Campbell</i>
3/3/31	4 th /N.S.P. Remodeling of 2 nd Story ^{Completed} <i>Al W. Campbell</i>
3/3/31	COMPLETED AND O.K. <i>Al W. Campbell</i> INSPECTOR