

## RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
3/5/65	Bldg. \$8,500.00	E-9810\$34.00	Const. new balcony in church sanctuary	Fremont Church	Chas F. Unger	Barbato	4/6/65
3/1/65	Bldg. \$1,800.00	E-9743	Const. storage for Church	Fremount Pres. Ch.	Chas Unger	Barbato	4/23/65
3/17/65	Bldg. \$200.00	E-9955\$5.00	Const. base house Trailer	Freemount Ch.	Owner	Chapin	8/3/65
1/20/66	Bldg. \$319,400	F-2885\$439.	Addn. classroom & social Hall;	Fremount Church	Nimbus Const.	Fuller	7/17/67
7/15/66	Bldg. \$14,500	F-4813\$52.	Const pass way for church	Nimbus Const.	Fremount Church	Fuller	6/8/68
12/15/66	Bldg. \$700.00	F-6069\$10.00	Const. office part. in ch.	Fremount Church	Owner	Fuller	6/8/67
5/16/72	Bldg. \$1,200.00	H-7076\$18.00	Reroof Church	Fremount Church	Owner	Fuller	8/28/72
12/5/75	Bldg. \$3,100.	C-9984\$39.	Reroof dwlg.	Fremount Church 5770 Carlson	Fred B. Curtis Inc. 1801 30th St.	NO FINAL INSPECTION CALLED BY PERMITEE.	
7/22/76	Bldg. \$900.00	D-5664\$15.00	Reroof dwelling	Fremount Church	Fred B. Curis 3 <sup>1</sup> / <sub>8</sub>	NO FINAL INSPECTION CALLED BY PERMITEE.	
5/9/77	Bldg. \$926.00	E-3225 \$30.00	Installation of Rudglas GLX 100-200 N/C Commer. Hot water heater	Fremount Pres. Church	Ray O. Cook, Mech. 5534 Elvas Ave.	Reynoso	8/3/77

## MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
E-9810	R-162F-442-443	F-4813	R-199F-21-222	E-3225	R-481F-255
E-9810	R-482F-292-final	F-4813	R-226F-442	E-3225	R-489F-485-final
E-9743	R-492-F-292-final	F-4813	R-492F-291-final	C-9984	Ⓟ 615F265 closed
E-9743	R-492 F-292-final	F-6069	R-207F-597-598	n-side 4	Ⓟ 615F265 closed
E-9955	R-492F-292-final	F-6069	R-492F-292-final		
E-9955	R-163F-397	H-7076	R-329F-99		
F-2885	R-185F-269-316	H-7076	R-492F-291-final		
F-2885	R-221F-298-300	C-9984	R-431F-044		
F-2885	R-492F-291-final	D-5664	R-450F-617		

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.	JOB ADDRESS 5770 Carlson Drive	
INSPECTION AREA	A-1	
	FINAL INSPECTIONS	
LEGAL DESCRIPTION	N.W. Corner Carlson Dr. & H-St 18x9 R 566E	
TITLE AND NAME	C.F. Unger Const	
GEN. CONTR.	2112 Sutterville Road	
ELEC. CONTR.		
PLBG. CONTR.		
MECH. CONTR.		
ARCH. ENGR.		
OWNER	Freemount P. Church	
CONST. LOAN LENDER	3600 J Street	
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT
NO. STORIES	ROOF CONSTR.	AREA 1st FLOOR
TOTAL AREA	C.S.D.	C.I. CASE
EXISTING BLDG'S SAME LOT		HOW USED
SIDE YARDS	REAR YARDS	SET BACK REQ.
USE ZONE	PARK'G REQ.	SPACES
TREES RMVD.	CENSUS TRCT. NO.	
ISSUED BY	DATE	
CERTIFICATE OF OCCUPANCY	MECHANICAL BY	
	DATE	
PLUMBING BY	DATE	
ELECTRICAL BY	DATE	
BUILDING BY	DATE	
6-24-63	7/11/63	

NATURE OF WORK:-  
Const Church and attached classrooms.

ISSUED BY	MICROFILM RECORD	
ISSUANCE DATE	3-2-62	
VALUATION	\$ 579,400	
PLANS AND APPLICATION	REEL NO. 96	FRAME NO.- 289
INSPECTION RECORD	REEL NO. 124	FRAME NO.- 353
JOB FILE	REEL NO.	FRAME NO.-
S.M.I. FEE	\$	
PLAN CK. FEE	\$	
SEWER INCL. FEE	\$	
PERMIT FEE	\$ 699.00	
TOTAL FEES	\$	

REMARKS AND/OR VARIANCES

R #92P303 - *Jma*