

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>6691</i>	LOCATION <i>2165 Franklin</i>		
DATE <i>8/9/30</i>	PURPOSE <i>Cost. Kitchen &amp; Bathroom</i>	ROOMS <i>2</i>	APTS. <i>1</i>
ZONE <i>Lin. Rez</i>	OWNER <i>R. Benton</i>	PHONE	
	ARCH'T		
	CONT'R <i>Demmer</i>		
	VAL. <i>500</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF			
Ex Wall	Jolts						Chimneys		Cement Tests
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
8/11/31	Made Preliminary Insp. of Additions being made between existing soft concrete Stand. Metal Clower I got this Permit and to fireproof wall but some with metal lath & sides of wall. OK Campbell
8/12/31	240 lbs. Frame for Add. in place. OK Campbell
8/12/31	300 lbs. Metal Lath " " OK Campbell
10/21-30	3 bit work & next work on P.H. Pickets
4-10-31	Finished 200 P.H. Pickets
	<p style="text-align: center;">COMPLETED AND O.K.</p> <p style="text-align: center;"><i>P.H.P.</i></p> <p style="text-align: right;">INSPECTOR</p>