

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS		
		3079 Bridgeford Drive					A-6			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
Larchmont Northgate #2 Lot 143									Riolo	12-14-70
TITLE AND NAME			1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE
GEN. CONTR. Owner										
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER Larchmont Northgate									CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA 467 Gar 1150 sq ft	C.S.D.	C.I. CASE		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE R-1	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:- Const. dwelling and garage MP #234

PERMIT NO. S.P. G-7621	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 285	FRAME NO:- 209	TO 215
ISSUANCE DATE Jul-22-70	INSPECTION RECORD	REEL NO. R410F596	FRAME NO:- 597	TO 600
VALUATION \$ 17,800	JOB FILE	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$	REMARKS AND/OR VARIANCES			
S.M.I. FEE \$	Form: 8-17-70 Riolo			
PLAN CK. FEE \$	Frame: 9-28-70 Riolo			
SEWER INCL. FEE \$	Sheet Rock: 10-2-70 Riolo			
PERMIT FEE \$				
TOTAL FEES \$ 68				