

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-14988</i>	LOCATION <i>117 - San Antonio Way</i>
DATE <i>1/14/46</i>	PURPOSE <i>Erect new dwlg & gar.</i>
ZONE	OWNER <i>Joe L. Bisset</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>68500</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
-------------------	---------------------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>100 sq ft</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
5/10/46	Form Insp. O. E. Buckius
9/16/46	Francis J. RB
COMPLETE AND O. K.	INSPECTOR