

*R-323 E-312*

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$12.00

TYPE BUILDINGS

PERMIT NO. H-5816	LOCATION 241 - Santiago Avenue A-7 (68)			
DATE Mar 9-72	PURPOSE Repair pest damage to dwelling	OWNER Mrs. M. Gust Same		
ZONE R-1	ARCH'T	CONT'R Paramount Pest Control 6405-Elvas Ave.		
VAL. \$800.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 452 6655
FORM	<i>3-29-72</i>	<i>[Signature]</i>		
JOIST				
FRAME SHEET ROCK	<i>3-29-72</i>	<i>[Signature]</i>		
FINAL	<i>4-10-72</i>	<i>[Signature]</i>		

20  
19  
18  
17  
16  
15  
14  
13  
12  
11  
10  
9  
8  
7  
6  
5  
4  
3  
2  
1

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<b>COMPLETE AND OK</b>
	<b>INSPECTOR</b>

