

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 9247</i>	LOCATION <i>1315-000</i>
DATE <i>10/3/41</i>	PURPOSE <i>Erect Club Room</i>
ZONE	OWNER <i>M. L. Lacey</i>
	ARCH'T. <i>Owens</i>
	CONTR. <i>Owens</i>

VAL. <i>2000</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
10/6/41	1 st / 1951. Forms for Club Bldg on rear of lot. Old Garage torn down to make room for same. O.K. R. W. Campbell
	COMPLETE AND O. K. INSPECTOR