

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>20 ch</i>	LOCATION <i>1311 P St Reno</i>			
DATE <i>7/24/32</i>	PURPOSE <i>Gen Rep to install Pm for Railor</i>			
ZONE <i>Industrial</i>	OWNER <i>Mrs Flynn</i>			
	ARCH'T			
	CONT-R <i>C. Athan</i>			
VAL. <i>Under 50+</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
4/30/37	<p>Reburs for Taylor Shop is "Non-Conforming" Building erected several years before Zoning Ordinance became effective. Completed A.W. Campbell</p>
	<p><i>(This section of the table is crossed out with a diagonal line.)</i></p>
4/30/37	<p>COMPLETE AND O. K. <i>A.W. Campbell</i> INSPECTOR</p>