

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-1231</i>	LOCATION <i>(rear) 320 - R St.</i>	
DATE <i>12/4/33</i>	PURPOSE <i>Repairs to Dwg. of Fire Damage</i>	PHONES
ZONE <i>In Com</i>	OWNER <i>A. Arnold</i>	
	ARCH'T	
	CONT-R	

VAL. <i>500.00</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
--------------------	------------------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
12/5/33	2 ND WSP Frame in Repair to 2 ND Story 2 front rooms damaged by fire
	O. R. A. W. Campbell
12/5/33	3 RD WSP. INT. WORK (PATCHING) ^{SR} A. W. Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>