

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-92055</i>	LOCATION <i>232 San Antonio Way</i>
DATE <i>1-7-51</i>	PURPOSE <i>Add two rooms & bath</i>
ZONE	OWNER <i>L. G. Kretz</i>
	ARCH'T.
	CONTR. <i>Oliver</i>

VAL. <i>\$ 1500</i>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
4/26/57	Frame Insp. (Ceiling Lsts. Truss and Flue Box.) O.K. D.E. Buckner
	COMPLETE AND O. K. INSPECTOR