

B1537314

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$10.00

TYPE BUILDINGS

| | | | | | |
|-----------------------------|-----------------|--|--------------|------------------------|----------------------|
| PERMIT NO. E-5659 | | LOCATION 2523 - V Street | | A-2 | |
| DATE Nov. 26-63 | | PURPOSE Repair termite damage to dwelling | | | |
| ZONE R-1 | | OWNER Don K. Wan | | Same | |
| | | ARCH'T | | | |
| | | CONTR Valley Termite 1617 - 18th Street | | | |
| VAL \$600. | | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | | | | | |
| JOIST | | | | | |
| FRAME | <i>12-11-63</i> | <i>Fields</i> | | | |
| SHEET ROCK | | | | | |
| FINAL | <i>12-17-63</i> | <i>Fields</i> | | | |

R

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|----------------------------|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |