

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
382-DuBois Ave.		6			
LEGAL DESCRIPTION					
Lot 219 Glenwood Park #1					
TITLE AND NAME					
1/c Owner					
GEN. CONTR.					
Owner					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
David E. Bohannon					
5888 Hillisdale Blvd.					
CERTIFICATE OF OCCUPANCY					
CONST. LOAN LENDER					
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR
			1		462 garage 1,304 sq. ft.
REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.
EXISTING BLDG'S SAME LOT					
HOW USED					
NATURE OF WORK:- Construct dwelling & garage MP#11-B-1					

ISSUED BY		MICROFILM RECORD	
ISSUANCE DATE		PLANS AND APPLICATION	
11/9/71		REEL NO. 315	
VALUATION		INSPECTION RECORD	
\$ 19,900.00		REEL NO. TO	
R.U.F. FEE		FRAME NO. TO	
\$		130	
S.M.I. FEE		JOB FILE	
\$		REEL NO. TO	
PLAN CK. FEE		FRAME NO. TO	
\$			
SEWER INCL. FEE		REMARKS AND/OR VARIANCES	
\$		1086 052 DWELLING	
PERMIT FEE		R*96F084 - final	
\$ 28.00			
TOTAL FEES			
\$			
\$			