

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-4048</i>	LOCATION <i>2959 San Jose Way</i>			
DATE <i>3/20/36</i>	PURPOSE <i>Make addition to rear</i>			
ZONE <i>2-Fam</i>	OWNER <i>San Pisani</i>			
	ARCH'T.			
	CON'TR. <i>Owner</i>			
VAL. <i>200⁰⁰</i>	STORIES	ROOMS <i>2</i>	APTS.	SIZE <i>9'-6" x 30'</i>
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK--REMARKS
	<p data-bbox="334 829 470 871">COMPLETE AND O. K.</p> <p data-bbox="1180 847 1312 871">INSPECTOR</p>