

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>Michy</i> DATE <i>1/23/20</i> ZONE	LOCATION <i>3218 Lockton Blvd</i>
	PURPOSE <i>Removal Pump</i>
	OWNER <i>Helen Bero</i>
	ARCH'T
	CONT'R <i>Asm</i>

PHONES

VAL. <i>80-</i>	STORIES	ROOMS	APTS.	SIZE
-----------------	---------	-------	-------	------

Steel Tested by	Elevator Shafts
Cement Tested by	Boiler Rooms
Owner's Inspector Rfcd. Conc.	Sprinkler System
Fire Escapes	Floor Tests
Stand Pipes	

DATE	CONDITION OF WORK - REMARKS
1/28/30	Made Partial Inspection - Owner removing old service station preparatory to erecting new steel & glass service station in place thereof. Also changing concrete frame. R.W. Campbell
2/1/30	1 st W.S.P. Form in place ^{OK} R.W. Campbell
COMPLETED AND O.K.	INSPECTOR