

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

<b>PERMIT NO.</b> B-37098	<b>LOCATION</b> 5324 Spilman Avenue			
<b>DATE</b> 2-4-53	<b>PURPOSE</b> Const. dwlg. and garage			
<b>ZONE</b>	<b>OWNER</b> D. L. Thomas			
	<b>ARCH'T.</b>			
	<b>CONTR.</b> Owner			
<b>VAL.</b> \$12,700.00	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<b>LIGHT SHAFTS</b>		<b>ELEVATOR SHAFTS</b>		
<b>VENT SHAFTS</b>		<b>BOILER ROOMS</b>		
<b>OWNER'S INSPECTOR</b>		<b>SPRINKLER SYSTEM</b>		
<b>LATH</b>		<b>GAS VENTS</b>		
<b>FIRE ESCAPES</b>		<b>CHIMNEYS</b>		
<b>STAND PIPES</b>		<b>SKYLIGHTS</b>		

DATE.	CONDITION OF WORK-REMARKS	
2-13-53	Form	Don W. Berry
3-13-53	Form	" "
4-7-53	Lath	" "
8-12-53	Final	" "
	<p><b>COMPLETE AND O. K.</b></p>	<p><b>INSPECTOR</b></p>