

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS		
		2851 Castro Way					3			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR.										
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER									CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED	

NATURE OF WORK:-

PERMIT NO. S.P. -	MICROFILM RECORD			
ISSUED BY				
ISSUANCE DATE	PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
VALUATION \$	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
R.U.F. FEE \$	JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE \$	<p style="text-align: center;">4897534-535 final</p>			
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$				
\$				
TOTAL FEES \$	REMARKS AND/OR VARIANCES			

2851 Castro Way

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
12/16/68	\$800.00	G-2188	Repair termite damage to dwelling	Bank of America	Midstate Termite	Fuller	12/16/68
3/25/27	\$4500.00	66	Resident	N. H. Lund	Owner	Campbell	5/31/27
MICROFILM RECORD							
PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
G-2182	R 251 R348						
G-2162	R 4189 R53						

Handwritten: G-2162
R 4189 R53
R 251 R348