

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-6045</i>	LOCATION <i>1325 Swanston Dr.</i>			
DATE <i>7/24/40</i>	PURPOSE <i>New duplex</i>			
ZONE <i>1</i>	OWNER <i>McClatchy Realty Co.</i>			
	ARCH'T.			
	CONTR. <i>Frank P. Williams</i>			
VAL. <i>7000⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1900^{sq}</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 35^{sq}</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE.	CONDITION OF WORK-REMARKS
7/26/40	1 st Insp Form OK <i>Inspector</i>
8/9/40	2 ND Insp. Frame in place ^{OK} <i>W. Campbell</i>
8/23/40	3 RD Insp INT & EXT LATH ^{OK} <i>W. Campbell</i>
9/25/40	4 TH Insp. Dwg. with attached base
	<i>Completed OK</i>
<i>9/27/40</i>	COMPLETE AND O. K. <i>William W. Campbell</i> INSPECTOR