

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-7018</i>	LOCATION <i>3984 - 2nd Ave</i>			
DATE <i>11/23/40</i>	PURPOSE <i>Repairs to store due to fire damage.</i>			
ZONE	OWNER <i>W. Simpson</i>			
	ARCH'T.			
	CONTR. <i>Chas Varina</i>			
VAL. <i>1700⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="314 871 455 912">COMPLETE AND O. K.</p> <p data-bbox="1251 888 1400 912">INSPECTOR</p>