

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. 839	LOCATION 3700 Franklin
DATE	PURPOSE By Br. rfr. rfr. rfr.
ISSUED ZONE RUC EXCEPT AS NOTED CONT'D DIVISION	OWNER Swinn Inc Co
	ARCHT
	CONT'R W.K. Co

PHONES

MAIL ROOM	STORIES	ROOMS	APTS.	SIZE 57' x 47'
-----------	---------	-------	-------	--------------------------

Steel Tested by	Elevator Shafts
Cement Tested by	Boiler Rooms
Owner's Inspector Rfd. Conc.	Sprinkler System
Fire Escapes	Floor Tests
Stand-pipes	

DATE	CONDITION OF WORK—REMARKS
8/1/27	1 ST /NSP. 12"X14" Concrete Footing for Buckle Hole ^{O.K.} N.W. Campbell
8/20/27	2 ND /NSP. Frame O.K. - N.W. Campbell
8/24/27	3 RD /NSP. INTERIOR LATH O.K. - N.W. Campbell
9/13/27	4 TH /NSP. Bldg Completed O.K. - N.W. Campbell
9/13/27	COMPLETED AND O. K. <i>Alfred N. Campbell</i> Inspector