

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$13.00					
TYPE BUILDINGS <i>R-111</i> <i>F251</i>					
PERMIT NO. E-2697	LOCATION 910 - Santa Ana Avenue A-6				
DATE Nov. 15-62	PURPOSE Const. addition to private garage	OWNER Ralph Dodrill 910-Santa Ave.			
ZONE R-1	ARCH'T	CONTR Chussey Bldg. & Const. 711-Cedar St.			
VAL. \$1,400.		STORIES	ROOMS	APTS.	No. Sac. SIZE 560-gar.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP		
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	<i>4-10-63</i>	<i>[Signature]</i>		<i>[Initials]</i>	



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12.10.62	Could not find. Call him
12.11.62	Pt wrong kind of mtd. Must be 5/8" S&S Fuller
12/31/62	Pt table end of house must be checked Count
3-25-63	Not completed SF 4-25-63 Count
4-3-63	Pt Truss not properly constructed Count
4-10-63	Pt mtd. Not to good, but safe. Cannot be used for existing and/or repairs Count
	COMPLETE AND OK
	INSPECTOR