

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS		
		672-Brickyard Drive					3			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
Basford Estates #1									Riolo	4-9-73
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR. Owner										
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER Lee Basford			5660 Havenside Dr.						CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
						2015				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:- Const. Dwlg. & Att. Garage & patio

PERMIT NO. S.P. H-9122	MICROFILM RECORD			
ISSUED BY				
ISSUANCE DATE Oct. 11- 1972	PLANS AND APPLICATION	REEL NO. R 375	FRAME NO. 264	TO
VALUATION \$ 30,300.00	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$	JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$ 108.00	REMARKS AND/OR VARIANCES			
\$	Dwelling			
\$				
TOTAL FEES \$				

