

R-67

Lot 3 BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD P 311-517

S. Ld. Pk. Terr. #10 **TYPE BUILDINGS** \$81.50

PERMIT NO. D-4860	LOCATION <i>RIVERSIDE Blvd</i> 4449 West Coast drive A-3
DATE Mar. 7, 60	PURPOSE Const 6-Unit Apartment
ZONE R-3	OWNER Stoddard & Bungay 1815 Silica
	ARCH'T Carter & Sparks
	CONT'R Stoddard Const 1815 Silica WA 2-7172

VAL. \$41,600.	STORIES 2	ROOMS 24	APTS. 6	SIZE 2700 Sq. ft.
----------------	--------------	-------------	------------	----------------------

INSP.	DATE	INSPECTOR
FORM	3-17-60	<i>(Young)</i> Count - Footings only. 3-21-60 Count
JOIST		
FRAME	4-15-60	Count - Roof Sheeting ok. Count
LATH	4-26-60	Lath ok - Count
FINAL	6-21-60	Count <i>with</i>

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
3-29-60	Forona (washrooms) OK Court
6-15-60	<p>P.T. Bldg. OK But down aprons not connected to storm sewer - Jones</p> <p>Roof not drained to curb. No city storm drain Jones</p>
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>