

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-2475</i>	LOCATION <i>1016 - 31<sup>st</sup> Street</i>			
DATE <i>2/17/39</i>	PURPOSE <i>Replace with Brick Wall</i>			
ZONE	OWNER <i>M. Protch</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>1850<sup>00</sup></i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
2/25/39	1 <sup>ST</sup> /NSP. 2 Brick Piers for Rear Porch <sup>OK</sup> <i>R.N. Campbell</i>
2/25/39	2 <sup>ND</sup> /NSP. Frame for new 12' Brick Wall on <i>Right</i> side and 2 - 6'x6' Posts to support <i>new</i> Porch Wall. <sup>OK</sup> <i>R.N. Campbell</i>
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="239 878 353 914">COMPLETE AND O. K.</span> <span data-bbox="1005 888 1126 909">INSPECTOR</span> </div>