

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

110-110-110-110

PERMIT NO. 7326	LOCATION 36 Sand Drive Terrace			APTS. 2	
	PURPOSE DUPLEX			ROOMS 10	APTS. 2
DATE 4/1/50	OWNER 1			PHONE	
ZONE 2-10m	ARCH'T Amundson				
	CONT'R Amundson				
	VAL. 4650	STORIES 2		SIZE	

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joists						Chimneys	
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
6-21/66	OK with moving is complete <i>Court</i>
9-2-66	ok say mail <i>Court</i>
11/7/66	PT Serial No OK by planning or city engineer. No down section reference next to B1 Zone <i>Callaway</i> No inspection tag.
COMPLETE AND OK	INSPECTOR