

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-7469</i>	LOCATION <i>937 - Robertson Way.</i>			
DATE <i>2/10/41</i>	PURPOSE <i>Erect new dwlg. garage</i>			
ZONE	OWNER <i>R. L. Fountain</i>			
	ARCH'T.			
	CONTR. <i>Frank Fountain</i>			
VAL. <i>4200<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1238<sup>00</sup></i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
2/12/41	1 <sup>st</sup> WSP. Forms in place of <i>W.C. Campbell</i>
3/28/41	2 <sup>nd</sup> WSP. Frame " " <i>OR W.C. Campbell</i>
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>