

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-24591</i>	LOCATION <i>1010 - 3rd street</i>			
DATE <i>2-23-49</i>	PURPOSE <i>Repairs to bldg front</i>			
ZONE	OWNER <i>McClatchy Realty</i>			
	ARCH'T.			
	CONTR. <i>Wayne Norris</i>			
VAL. <i>\$ 800</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
3/17/49	Removed Cornice, Painted-up Wall, & Anchored Wall at Roof Line (P.E. Buckline)
	COMPLETE AND O. K. INSPECTOR