

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|-----------------------------|---|
| PERMIT NO. <i>B-9619</i> | LOCATION <i>3750 - Stockton Bldg</i> |
| DATE <i>11/29/41</i> | PURPOSE <i>Market Bldg.</i> |
| ZONE | OWNER <i>J. G. Sudder</i> |
| | ARCH'T. <i>Duncan</i> |
| | CONTR. |

| | | | | |
|---------------------------------|------------------|----------------|-------|------|
| VAL. <i>13,500⁰⁰</i> | STORIES <i>1</i> | ROOMS <i>5</i> | APTS. | SIZE |
|---------------------------------|------------------|----------------|-------|------|

| | |
|-------------------|------------------|
| LIGHT SHAFTS | ELEVATOR SHAFTS |
| VENT SHAFTS | BOILER ROOMS |
| OWNER'S INSPECTOR | SPRINKLER SYSTEM |
| LATH | GAS VENTS |
| FIRE ESCAPES | CHIMNEYS |
| STAND PIPES | SKYLIGHTS |

| DATE | CONDITION OF WORK—REMARKS |
|--------|---|
| | |
| 1/2-42 | 2 nd Insp Frame of United |
| 5/6-42 | Frame Insp'n on South Abt. of |
| | Reactor |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p> |